

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Fig. 1




Fig. 2




Fig. 3




Fig. 4A




Fig. 4B




Fig. 4C




Fig. 5A




Fig. 5B




Fig. 6




Fig. 7




Fig. 8







Fig. 9







FIG. 10: U-Strip Test Set Rig.

Fig. 11






Figure 12 A

Image 1

Scan #21 Baseline Scan of Abdomen Control Site

Depth capture 5.1 mm

**Control Scan (No Ultrasound), Saline left
upon Skin surface**




Figure 12 B

Image 2

#28 45 min with unplowed transducer.

Depth capture 5.1mm




Figure 12 C

Image 3

Scan #25: 45 min treated

(#5 set, # 8 transducer)

Saline Pushed By Ultrasound To 5.2 mm Depth through Abdominal Skin




Figure 12 D

Image 4

Scan# 32 – 90 min untreated.
Unpowered transducer.

Depth capture 10.2mm




Figure 12 E

Image 5

Scan # 33 – 90 min treated.
Powered transducer.

Depth capture 10.2mm